



Intel[®] 815 Chipset Family: 82815 Graphics and Memory Controller Hub (GMCH)

Specification Update

May 2001

Notice: The Intel[®] 82815 GMCH may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

Document Number: 298253-003

Information in this document is provided in connection with Intel® products.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document.

Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right.

Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® 82815 GMCH may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation

www.intel.com

or call 1-800-548-4725

Intel and Pentium III are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2000–2001, Intel Corporation



Contents

Revision History..... 4

Preface..... 5

Specification Changes..... 9

Errata..... 11

Specification Clarifications 15

Documentation Changes..... 17

Revision History

Rev.	Draft/Changes	Date
-001	Initial Release: Specification Changes # 1– 2; Errata # 1 – 5; Specification Clarification # 1– 3.	August 2000
-002	Added Errata #6; Added Specification Clarification #4.	January 2001
-003	Added Specification Clarifications # 5 – 7; Added Documentation Change #1	May 2001

Preface

This document is an update to the specifications contained in the documents listed in the following Affected Documents/Related Documents table. It is a compilation of device and document errata and specification clarifications and changes, and is intended for hardware system manufacturers and for software developers of applications, operating system, and tools.

Information types defined in the Nomenclature section of this document are consolidated into this update document and are no longer published in other documents. This document may also contain information that has not been previously published.

Affected Documents/Related Documents

Document Title	Document Number
<i>Intel® 815 Chipset Family: 82815 Graphics and Memory Controller Hub (GMCH) datasheet</i>	290688-001

Nomenclature

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Errata are design defects or errors. Errata may cause the Intel®815 chipset behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

Component Identification via Programming Interface

The Intel® 82815 GMCH may be identified by the following register contents:

Stepping	Device	Vendor ID ¹	Device ID ²	Revision Number ³
A0	0	8086h	1130h	00h
	1	8086h	1131h	00h
	2	8086h	1132h	00h
A1	0	8086h	1130h	01h
	1	8086h	1131h	01h
	2	8086h	1132h	01h
A2	0	8086h	1130h	02h
	1	8086h	1131h	02h
	2	8086h	1132h	02h

NOTES:

1. The Vendor ID corresponds to bits 15-0 of the Vendor ID Register located at offset 00-01h in the PCI function 0 configuration space of Device 0, 1, 2.
2. The Device ID corresponds to bits 15-0 of the Device ID Register located at offset 02-03h in the PCI function 0 configuration space of Device 0, 1, 2.
3. The Revision Number corresponds to bits 7-0 of the Revision ID Register located at offset 08h in the PCI function 0 configuration space of Device 0, 1, 2.

Component Marking Information

The Intel 82815 GMCH can be identified by the following component markings:

Stepping	S-Spec	Top Marking	Notes
A0	Q921	FW82815	
A1	Q963	FW82815	
A1	Q964	FW82815	
A2	SL4DF	FW82815	Production 82815 GMCH

Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the listed Intel® 815 chipset stepping. Intel intends to fix some of the errata in a future stepping of the component and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

X: Erratum, Specification Change or Clarification that applies to this stepping.

(No mark) or (Blank Box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Status

Doc: Document change or update that will be implemented.

Fix: This erratum is intended to be fixed in a future stepping of the component.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

Eval: Plans to fix this erratum are under evaluation.

Other

Shaded: This item is either new or modified from the previous version of the document.

Number	SPECIFICATION CHANGES
1	SWE#, SCAS#, SRAS#, SMAA[11:8,3:0], and SBS[1:0] Signal Buffer Strength Programming
2	DRAMT – DRAM Timing Register (Device 0), Address Offset 53h, Bit 3

Number	Steppings		Plans	ERRATA
	A2			
1	X		Fix	Host Interface Buffer Noise
2	X		No Fix	System Bus Snoop
3	X		No Fix	Asynchronous Screen Flip
4	X		No Fix	System Memory Data Line
5	X		No Fix	System Memory Frequency
6	X		No Fix	False Device 1 System Error Message

Number	SPECIFICATION CLARIFICATIONS
1	Section 1.5: System Memory Interface
2	Section 4.5: System Memory DRAM Interface
3	Section 4.5.2: DRAM Address Translation and Decoding
4	Only AGP4X Cards Which Use Differential Clocking Mode Are Supported
5	The 82815 Does Not Support Intel® Pentium® III Processors That Use 0.13 μ Technology
6	Chipsets in the Intel® 815 Chipset Family
7	The 82815 Does Not Support Intel® Pentium® III Processors That Use 0.13 μ Technology

Number	DOCUMENTATION CHANGES
1	82815 544 BGA Ball-Out Package Dimensions Is Corrected

Specification Changes

1. SWE#, SCAS#, SRAS#, SMAA[11:8,3:0], and SBS[1:0] Signal Buffer Strength Programming

Regardless of system memory interface frequency, the SMAA [11:8, 3:0], SBS [1:0] SWE#, SCAS#, and SRAS# signal buffer strengths for all rows should be set accordingly to the DIMM loading which is defined in the table below. This affects the BUFF_SC – System Memory Buffer Strength Control Register, Device0, Reg92h [1:0].

Reference Section 3.4.24, *BUFF_SC—System Memory Buffer Strength Control Register*.

1:0	<p>SWE#, SCAS#, SRAS#, SMAA[11:8, 3:0], SBS[1:0] Control Buffer Strengths (All Rows)</p> <p>00 = 1.7x > 32 loads 01 = 0.7x < 8 loads 10 = 1.0x 8-32 loads 11 = 1.0x 8-32 loads</p> <p>The load on the Address and Control signals (other than SMA*[7:4] above) is simply the number of devices populated in ALL rows (range from 4 to 48 loads!).</p> <p style="text-align: center;">Loads = (64 / Row 0 Device Width) + (64 / Row 1 Device Width) + (64 / Row 2 Device Width) + (64 / Row 3 Device Width) + (64 / Row 4 Device Width) + (64 / Row 5 Device Width)</p>
-----	--

2. DRAMT – DRAM Timing Register (Device 0), Address Offset 53h, Bit 3

Reference the *Intel® 815 Chipset Family: 82815 Graphics and Memory Controller Hub (GMCH)* datasheet, Section 3.4.17, *DRAMT – DRAM Timing Register*. The description for bit 3 is changed from “Intel Reserved” to show the following:

7	5	4	3	2	1	0
SDRAM Mode Select		DRAM Cycle Time	Host Aperture Cycle Queue Slot	CAS# Latency	SDRAM RAS# to CAS# Dly	SDRAM RAS# Precharge

Bit	Description
3	<p>Host Aperture Cycle Queue Slot</p> <p>0 = Default value. No dedicated queue slot is reserved for host to aperture cycles. 1 = A dedicated queue slot is reserved for host to aperture cycles.</p> <p>The BIOS should set this bit to '1'.</p>

This page is intentionally left blank.

Errata

1. Host Interface Buffer Noise

Problem: False assertions of H_ADS# signal observed on-die on the A-2 stepping of the Intel 815 chipset (GMCH).

Implication: System hangs or boot failures can occur with A-2 stepping of Intel 815 chipset based platforms.

Workaround: Increase spacing between nearest neighbor system memory and GTL+ buffers. Reduce System Memory buffer strength settings for 100/133.

Status: The Root Cause of this errata was found to be cross coupling of system memory signals onto nearest neighbor GTL+ signals (specifically H_ADS#) on the board, package, and die. The A-2 stepping of the Intel 815 chipset will include circuit changes to improve the noise immunity of GTL+ buffers.

2. System Bus Snoop Logic

Problem: Under specific sequence of bus cycles, data from the wrong address may be returned to the graphics controller. This can occur if the following three conditions align:

1. Back-to-back ADS# on the system bus
2. PHOLD (ISA Master) access on the hub interface

Status: External graphics AGP snoop OR internal graphics cacheable BLTs/Store DWORD.

Implication: If the data from the wrong address is returned to the graphics controller, either graphics corruption or system hang can occur.

Workaround: None

Status: This Issue has only been observed in a System Validation Environment with a specific focus test. This issue has not been observed with any real applications tested. There are no plans to fix this erratum.

3. Asynchronous Screen Flip

Problem: When the Intel 815 chipset A-2 step is configured for asynchronous screen flipping, under certain timing-dependent circumstances the display engine may temporarily read pixel data from a random memory location.

Implication: When changing display surfaces using the asynchronous screen flipping, subtle display corruption is seen in the form of short, somewhat random colored, horizontal lines along the left side of the screen.

Workaround: Driver version 4.1.1 does, and future versions will, disable asynchronous screen flipping for commonly used 3D resolutions.

Status: There are no plans to fix this erratum in silicon.

4. System Memory Data Line Noise

Problem: When the Intel 82815 A-2 step GMCH has multiple system memory data lines transition from low to high, a glitch can appear on non-switching data lines.

Implication: The erratum is amplified by trace impedance and discontinuities on the motherboard and DIMM. When measured at the SDRAM pin, it can violate the published V_{IL} specification of SDRAM components in the valid timing window. In this case, incorrect data could be clocked into the SDRAM causing data corruption.

Workaround: To minimize amplification of the glitch on the board:

- Follow published design specifications detailed in the *Intel® 82815 Chipset Platform Design Guide*, dated June 2000, Order Number 298233-001, para 5.2 and 5.4. For the 82815E, follow published design specifications detailed in the *Intel® 82815E Chipset Platform Design Guide*, dated June 2000, Order Number 298234-001, para 5.2 and 5.4.
- Implement buffer strength and System Memory RCOMP.

Status: There are no plans to fix this erratum in silicon.

5. System Memory Frequency Select

Problem: Register 50h (GMCHCFG) bit 2 of the Intel 82815 A-2 step is set incorrectly when a 66 MHz Front Side Bus processor is plugged into the system.

Implication: When the Intel 82815 GMCH A-2 step sets this bit at reset with a 66 MHz Front Side Bus processor plugged into the system, this bit will be set incorrectly.

Workaround: BIOS must detect if a 66 MHz Front Side Bus processor is plugged into the system and set this bit to '0' to indicate 100 MHz system memory.

Status: There are no plans to fix this erratum in silicon.

6. **False Device 1 System Error Message**

Problem: A false Signal System Error (SERR) is generated when Device 1 system error signaling is enabled. The false SERR results in the generation of a Non-Maskable Interrupt (NMI).

Implication: A false error is detected and the system may halt.

Workaround: Disable Device 1 SERR Message Enable by setting PCICMD1 - PCI-PCI Command Register (Device 1), address offset 04h-05h, bit [8] to “0”. This is the existing BIOS default setting for this bit.

Status: There are no plans to fix this erratum in silicon.

This page is intentionally left blank.

Specification Clarifications

1. Section 1.5: System Memory Interface

This section has been changed to correctly read, “The GMCH supports industry standard 64-bit wide DIMMs with SDRAM devices. The thirteen multiplexed address lines (SMAA[12:0]) along with the two bank select lines (SBS[1:0]) allow the GMCH to support 2M, 4M, 8M, 16M, and 32M x64 DIMMs.”

2. Section 4.5: System Memory DRAM Interface

This section has been changed to correctly read, “The 2 bank select lines (SBS[1:0]), the 13 address lines (SMAA[12:0]), and copies of 4 address lines (SMAB[7:4]# and SMAC[7:4]#) allow the GMCH to support 64-bit wide DIMMs using 16-Mb, 64-Mb, 128-Mb, or 256-Mb technology SDRAMs.”

3. Section 4.5.2: DRAM Address Translation and Decoding

This section has been changed to correctly read, “The GMCH supports 16-Mbit, 64-Mbit, 128-Mbit, and 256-Mbit SDRAM devices.”

4. Only AGP4X Cards Which Use Differential Clocking Mode Are Supported

Section 1.6.1, *AGP Interface*: The following line is added to the section:

“The Intel 82815 chipset only supports AGP4X cards that use differential clocking mode.”

5. The 82815 Does Not Support Intel® Pentium® III Processors That Use 0.13 μ Technology

Intel® 815 Chipset Family: 82815 Graphics and Memory Controller Hub (GMCH) datasheet Features List, Processor/Host Bus Support. Insert the following item in the list:

- Does not support Intel® Pentium® III processors that use 0.13 μ technology.

6. Chipsets in the Intel® 815 Chipset Family

Reference *Section 1, Overview*. Insert the following material to replace the paragraph beginning, “There are two chipsets...”

There are five chipsets in the Intel® 815 chipset family:

- Intel® 82815 chipset: This chipset contains the 82815 and the 82801AA ICH.
- Intel® 82815E chipset: This chipset contains the 82815E and the 82801BA ICH2.
- Intel® 82815EP chipset: This chipset contains the 82815EP and the 82801BA ICH2. There is no internal graphics capability. This GMCH uses an AGP port only.

- Intel® 82815G chipset: This chipset contains the 82815G GMCH and 82801AA ICH. There is no AGP port capability and no display cache capability. This GMCH uses internal graphics only.
- Intel® 82815EG chipset. This chipset contains the 82815EG GMCH and 82801BA ICH2. There is no AGP port capability and no display cache capability. This GMCH uses internal graphics only.

Note: The only component difference between the Intel 82815 GMCH and the Intel 82815E GMCH is the I/O Controller Hub. The only component difference between the Intel 82815G GMCH and the Intel 82815EG GMCH is the I/O Controller Hub.

7. The 82815 Does Not Support Intel® Pentium® III Processors That Use 0.13 μ Technology

Reference Section 1.4, *Host Interface* in the datasheet. Add the following information to the first paragraph:

The 82815 GMCH will not support Intel Pentium III processors that use 0.13 μ technology. These processors should not be placed in platforms using the 82815 GMCH. Future versions of the Intel 815 chipset family will support Intel Pentium III processors that use 0.13 μ technology.

Documentation Changes

1. 82815 544 BGA Ball-Out Package Dimensions Is Corrected

Reference Section 5.2, *Package Information*, in the datasheet. Replace Figure 13 with the following correct 544 BGA ball-out bottom view:

