



# Monthly Specification Update

## *Intel<sup>®</sup> Server Board S2600CO Family*



October, 2012

Enterprise Platforms and Services Marketing

## ***Revision History***

<b>Date</b>	<b>Modifications</b>
May, 2012	Initial release.
July,2012	Add errata 12-21
October,2012	Add errata 22,23 and update errata 2,4,7,9,12-17,19

## ***Disclaimers***

The Monthly Specification Update Server System may contain design defects or errors known as errata that may cause the product to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel<sup>®</sup>'s Terms and Conditions of Sale for such products, Intel<sup>®</sup> assumes no liability whatsoever, and Intel<sup>®</sup> disclaims any express or implied warranty, relating to sale and/or use of Intel<sup>®</sup> products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel<sup>®</sup> products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel<sup>®</sup> sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Itanium, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

\*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2012.

# Contents

**Preface**..... 1

    Nomenclature ..... 1

    Product Scope ..... 1

**Summary Tables of Changes** ..... 2

**Errata** ..... 4

    1. Linux Operating Systems are not supported using the RSTe mode..... 4

    2. UEFI Windows Server 2008\* R2 SP1 installation on SCU ports may fail under RSTe RAID mode ..... 4

    3. UEFI Operating System installation is not supported using the ESRT2 mode ..... 4

    4. HDD status LEDs do not function under specific configuration ..... 5

    5. RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports 5

    6. BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller 5

    7. System may halt under specific BIOS configurations..... 6

    8. Microsoft Windows 2003\* x86 installation failure occurs using the “Pass-Through” mode of the SCU controller ..... 6

    9. System may halt under unsupported configuration in ESRT2 mode ..... 6

    10. Extra events may be seen in the System Event Log (SEL) during system global reset 7

    11. System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs ..... 7

    12. Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero 8

    13. Integrated BMC Web Console – Power Control page – Perform Action button not functional 8

    14. IPMI Get Chassis Status command returns incorrect Chassis Identify State ..... 8

    15. The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility(OFU) under SuSE Linux Enterprise Server 11\* (64-bit) with SP2..... 9

    16. BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under the ESRT2 mode of the SCU controller ..... 9

    17. High CPU utilization may occur when installing or running Microsoft\* Windows\* Server 2008 R2 or Microsoft\* Windows\* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET .... 9

    18. Intel® RAID C600 Upgrade Key replacement Issue ..... 11

    19. Intel® LAN driver installation failure on Windows\* 7 ..... 11

    20. Hard drives connected through SAS expander can't be detected in legacy mode 11

    21. On-board VGA cannot be set to the highest resolution (1920x1080 and higher). .12

    22. Integrated BMC Web Console – Sensor Readings Page – Memory Throttling sensor status will stay “Critical” once triggered ..... 12

    23. WOL (Wake on LAN) may not be function under Red Hat\* Linux 6.2 64bit OS..... 13

Documentation Changes ..... 14

<This page is intentionally left blank.>



## Preface

---

This document is an update to the specifications contained in the *Intel® Server/Workstation Board S2600IP/W2600CR and Intel® Server/Workstation System P4000IP/CR, R2000IP Technical Product Specification*. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain specification changes, specification clarifications, errata, and document changes.

### Nomenclature

1. **Specification Changes** are modifications to the current published specifications for Intel® server boards. These changes will be incorporated in the next release of the specifications.
2. **Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.
3. **Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.
4. **Errata** are design defects or errors. Errata may cause the server board behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that processor stepping are present on all devices.

### Product Scope

The following specific boards, BIOS and components are covered by this update:

Product Code	Baseboard PBA Revision	BIOS Revision	BMC Revision	FRU/SDR Revision	ME Revision
DBS2600COE	G29920-204	01.01.1002	1.00	1.03	02.01.05.069
BBS2600CO4	G35870-203	01.01.1002	1.00	1.03	02.01.05.069
BBS2600COE	G29920-204	01.01.1002	1.00	1.03	02.01.05.069
DBS2600COEIOC	G29920-204	01.01.1002	1.00	1.03	02.01.05.069

## Summary Tables of Changes

The following tables provide an overview of known errata and known document changes that apply to the specified Intel Server Products. The tables use the following notations:

**Doc:** Intel intends to update the appropriate documentation in a future revision.

**Fix:** Intel intends to fix this erratum in the future.

**Fixed:** This erratum has been previously fixed.

**No Fix:** There are no plans to fix this erratum.

**Shaded:** This erratum is either new or has been modified from the previous specification update.

**Table 1. Errata Summary**

No.	Plans	Description of Errata
1.	Fix	Linux Operating Systems are not supported on RSTe mode
2.	Fixed	UEFI Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode
3.	Fix	UEFI Operating System installation is not supported on ESRT2 mode
4.	Fixed	HDD status LEDs do not function under specific configuration
5.	Fix	RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports
6.	Fixed	BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller
7.	Fixed	System may halt under specific BIOS configurations
8.	Fixed	Microsoft Windows 2003* x86 installation failure under Pass-through mode of SCU controller
9.	Fixed	System may halt under unsupported configuration in ESRT2 mode
10.	Fixed	Extra events may be seen in the System Event Log (SEL) during system global reset
11.	Fixed	System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs
12.	Fixed	Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero
13.	Fixed	Integrated BMC Web Console – Power Control page – Perform Action button not functional.
14.	Fixed	IPMI Get Chassis Status command returns incorrect Chassis Identify State
15.	Fixed	The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility (OFU) under SuSE Linux Enterprise Server 11* (64-bit) with SP2
16.	Fixed	BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under ESRT2 mode of the SCU controller
17.	Fixed	High CPU utilization may occur when installing or running Microsoft* Windows* Server 2008 R2 or Microsoft* Windows* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET
18.	Fixed	Intel® RAID C600 Upgrade Key replacement Issue
19.	Fixed	Intel® LAN driver installation failure on Windows* 7
20.	Fix	Hard drives connected through SAS expander can't be detected in legacy mode



No.	Plans	Description of Errata
21	Fix	On-board VGA cannot be set to the highest resolution (1920x1080 and higher).
22	Fix	Integrated BMC Web Console – Sensor Readings Page – Memory Throttling sensor status will stay “Critical” once triggered
23	Fix	WOL (Wake on LAN) may not function under Red Hat* Linux 6.2 64bit OS

Table 2. Documentation Changes

No.	Plans	Document Name	Description of Documentation Change
1.			
2.			
3.			
4.			

The following sections provide in-depth descriptions of each erratum/documentation change indicated in the tables above. The errata and documentation change numbers referenced in the following sections correspond to the numbers in the tables above.

## Errata

---

### 1. Linux Operating Systems are not supported using the RSTe mode

Problem	Intel® RSTe mode is not supported on Red Hat* Linux and SUSE* Linux.
Implication	User may not be able to install Red Hat* Linux and SUSE* Linux on Intel® C600 Series Chipset based Server Boards under Intel® RSTe mode.
Status	This issue may be fixed in a future driver or BIOS release.
Workaround	None.

### 2. UEFI Windows Server 2008\* R2 SP1 installation on SCU ports may fail under RSTe RAID mode

Problem	System may encounter blue screen when installing Windows Sever 2008* R2 SP1 under UEFI with below configurations: <ul style="list-style-type: none"><li>i. Intel® C600 RAID Upgrade Key is installed and SAS HDDs are used on SCU ports.</li><li>ii. BIOS options “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are enabled.</li><li>iii. RSTe RAID mode is used.</li></ul>
Implication	User may not be able to install UEFI Windows Server 2008* R2 SP1 on Intel® C600 Series Chipset based Server Boards with the above mentioned configuration.
Status	This issue was fixed in BIOS 01.06.0001 release.
Workaround	None.

### 3. UEFI Operating System installation is not supported using the ESRT2 mode

Problem	UEFI OS installation of Windows*, Red Hat* Linux or SUSE* Linux may fail on AHCI or SCU controller when “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are both enabled.
---------	--

Implication	User may not be able to install UEFI OS under the ESRT2 mode on Intel® C600 Series Chipset based Server Boards
Status	This issue may be fixed in a future BIOS revision.
Workaround	None.

#### **4. HDD status LEDs do not function under specific configuration**

Problem	If drives are connected through expander to SCU ports and configured under RSTe mode, the HDD status LEDs may not function properly.
Implication	HDD status LED may not show the HDD locate, HDD fault or RAID rebuild message.
Status	This issue was fixed in RSTe driver 3.2.0.1134 and later version.
Workaround	None.

#### **5. RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports**

Problem	When Microsoft Windows 2008* R2 is installed on SCU ports, the installation of RSTe drivers and the Graphic User Interface (GUI) in Windows 2008* R2 will fail, if the AHCI controller is enabled, and no devices are attached to the AHCI SATA ports.
Implication	User may not be able to install RSTe GUI under mentioned configuration when the AHCI controller is enabled and no devices are attached to the AHCI SATA ports.
Status	This issue may be fixed in a future RAID driver.
Workaround	The workaround is to either plug a SATA device into one of the AHCI SATA ports or disable the onboard AHCI controller in BIOS

#### **6. BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller**

Problem	When RSTe RAID is in degraded mode and a drive is inserted to start the RAID rebuild, System Event Log (SEL) records drive plug and rebuild events and then continuously sends a rebuild event message.
---------	---

Implication	User may see the SEL flooded with RAID volume rebuild event entries.
Status	This issue was fixed in the latest RSTe driver ver 3.0.0.3020 upd 2012.02.03.
Workaround	None.

## 7. System may halt under specific BIOS configurations

Problem	Once BIOS options “EFI Optimized Boot” and “Memory Mapped I/O Above 4GB” are enabled, and RSTe mode is selected, system may halt during POST.
Implication	User may see system hang with the above mentioned configuration.
Status	This issue was fixed in Bios 01.03.0002 release.
Workaround	None.

## 8. Microsoft Windows 2003\* x86 installation failure occurs using the “Pass-Through” mode of the SCU controller

Problem	Microsoft Windows Server 2003* x86 installations on SCU RSTe “pass-through” mode fail.
Implication	User may not able to install Microsoft Windows Server 2003* x86 on the above mentioned BIOS configuration.
Status	This issue was fixed in the latest RSTe driver ver 3.0.0.3020 upd 2012.02.03
Workaround	None.

## 9. System may halt under unsupported configuration in ESRT2 mode

Problem	If no Intel® C600 RAID upgrade key (any of RKSAS4, RKSAS4R5, RKSAS8, RKSAS8R5) is installed to enable SAS support capability under the ESRT2 mode and SAS drivers are used, the system may halt at the boot stage.
Implication	User may see a system halt with no RAID keys installed with SAS drivers used and ESRT2 enabled. User should use SATA drives only if no RAID key installed.
Status	This issue was fixed in Bios01.03.0002 BIOS release.

Workaround None.

## 10. Extra events may be seen in the System Event Log (SEL) during system global reset

**Problem** The BMC may sporadically log extra reset event during a system DC reset (global reset). These events may appear as there is an extra reset during BIOS POST.

The following SEL entries indicate two resets in a POST process:

*Informational event: Pwr Unit Status reports the power unit is powered off or being powered down.*

*Informational event: Pwr Unit Status reports the power unit is powered off or being powered down.*

**Implication** The SEL log may indicate that system has an occasional reset in a normal POST during DC cycle test (global reset).

**Status** This issue was fixed in BMC 1.04.

**Workaround** None.

## 11. System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs

**Problem** With ESRT2 SATA RAID 5 config with 3 HDDs, put the 4th HDD in drive carrier and set it to either unconfigured or global hot spare. System event log may be flooded with HDD faulty entries.

With ESRT2 SAS RAID 1 with 2 HDDs, put 3rd HDD and set to unconfigured or global hot spare. System event log may be flooded flood with HDD faulty entries.

**Implication** User may see the SEL flooded with HDD faulty entries when either of the two scenarios above are used.

**Status** This issue was fixed in BMC 1.04.

**Workaround** None.

## 12. Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero

Problem	On some systems the Integrated BMC Web Console Power Statistic page may display the Minimum wattage as zero (0W) after the system has been powered. This reading will stay at zero until the next power cycle of the system.
Implication	This is an incorrect reading only and does not affect operation.
Status	This issue was fixed in BMC 1.10.r3560 release.
Workaround	None.

## 13. Integrated BMC Web Console – Power Control page – Perform Action button not functional

Problem	After performing a Graceful shutdown from the Integrated BMC Web Console Power Control page the Perform Action button is greyed out and cannot be pressed to request another action.
Implication	You cannot perform a power on of the system.
Status	This issue was fixed in BMC 1.10.r3560 release.
Workaround	Select another page in the Integrated BMC Web Console and then return to the Power Control Page. The Perform Action button will then be available.

## 14. IPMI Get Chassis Status command returns incorrect Chassis Identify State

Problem	When a Get Chassis Status command is issued, after the Chassis Identify LED has been forced on, the status of off (00b) is returned for Chassis Identify State (response data byte 4 – bits [5:4]).
Implication	Unable to correctly read when the Chassis Identify LED is on.
Status	This issue was fixed in BMC 1.10.r3560 release.
Workaround	None.

### 15. The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility(OFU) under SuSE Linux Enterprise Server 11\* (64-bit) with SP2

Problem	OFU will fail to update BIOS & ME under SuSE Linux Enterprise Server 11* (64-bit) with SP2 Operating System.
Implication	If the system is running SuSE Linux Enterprise Server 11* (64-bit) with SP2 Operating System, using OFU to update System Firmware Update Package(SFUP) will fail.
Status	This issue was fixed in OFU Version 11.0 Build 8.
Workaround	Update System Firmware Update Package(SFUP) from EFI environment using iFlash32, FWPIAUpdate and FRUSDR Utility.

### 16. BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under the ESRT2 mode of the SCU controller

Problem	HDD fault will keep asserting and de-asserting frequent during RAID rebuild under ESRT2.
Implication	During HDD ESRT2 RAID rebuild, there's flood HDD fault assert/deassert(SAS RAID) or Rebuild/remap (SATA RAID) logs into SEL.
Status	This issue was fixed in ESRT2 drivers 15.00.0528.2012 release.
Workaround	None.

### 17. *High CPU utilization may occur when installing or running Microsoft\* Windows\* Server 2008 R2 or Microsoft\* Windows\* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET*

Problem	There has been high CPU load observed when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC (Network Interface Card) driver.
Implication	When the ports are not electrically "linked" and the embedded driver is loaded the DPC rate steadily increases until the system slows to the point where it is essentially unusable.

Status            This issue was fixed in NIC driver 16.8 release.

Workaround      None.



## 18. Intel® RAID C600 Upgrade Key replacement Issue

Problem	With Manageability Engine (ME) Firmware 02.01.05.069, the server may detect the incorrect Storage Control Unit (SCU) Redundant Array of Inexpensive/Independent Disks (RAID) information after installing or replacing the RAID upgrade key. The board or system may still show the previous RAID information even if you replace the key with a new one.
Implication	With the ME firmware 02.01.05.069, the system may not detect the new RAID activation key during the first time AC power on.
Status	The issue is fixed with ME firmware 02.01.05.091.
Workaround	Do a second AC power cycle to the system after the RAID upgrade key has been installed or replaced to ensure the correct type of key is identified.

## 19. Intel® LAN driver installation failure on Windows\* 7

Problem	The Intel® LAN driver version 16.8 and below may not be installed successfully on Windows* 7 with the .bat installation scripts in the driver package.
Implication	The LAN driver can not be installed by the .bat installation scripts in the driver package.
Status	The issue was fixed in a Intel® LAN driver version 17.1 release.
Workaround	Two workarounds are available: <ol style="list-style-type: none"><li>1. The LAN driver can be manually installed.</li><li>2. User can lower the “User Account Control” to “Never Notify”, then the driver can be installed with the .bat installation scripts.</li></ol>

## 20. Hard drives connected through SAS expander can't be detected in legacy mode

Problem	If hard drives are connected through expander to SCU ports and configured under RSTe mode, the hard drives can't be detected by system in legacy mode (default BIOS setting).
Implication	Users can't use the hard drives connected through expander as boot device to install OS. But users can install OS to other hard drives which are not connected through expander and load RSTe driver to make the hard drives connected through expander visible to OS. Or users can change Boot Options -> EFI Optimized Boot to "Enabled" in BIOS Setup so that hard drives connected through expander can be detected by the system.
Status	This issue may be fixed in a future BIOS release.
Workaround	None.

## 21. On-board VGA cannot be set to the highest resolution (1920x1080 and higher).

Problem	The Graphics ID register in the on-board video controller is getting set incorrectly.
Implication	The video cannot be set to the highest resolutions listed here: [1920x1080,High 256 Color, 60 Hertz] [1920x1200,High 256 Color, 60 Hertz] [1920x1080,High Color(16bit), 60 Hertz] [1920x1200,High Color(16bit), 60 Hertz]
Status	This issue may be fixed in a future BMC release.
Workaround	None.

## 22. *Integrated BMC Web Console – Sensor Readings Page – Memory Throttling sensor status will stay “Critical” once triggered*

Problem	When Memory Throttling is triggered, the Memory “P1 MTT and/or P2 MTT” sensor status will stay at “Critical” status in the Integrated BMC Web Console even after throttling has stopped.
Implication	You may observe Memory “P1 MTT and/or P2 MTT” status as “Critical” even when there is no throttling. No functional impact to the system.

Status This issue may be fixed in a future ME release.

Workaround Need a AC cycle or reset ME through IPMI to reset the MTT sensor status.

### *23. WOL (Wake on LAN) may not be function under Red Hat\* Linux 6.2 64bit OS*

Problem With Intel® LAN driver version 17.1, WOL (Wake on LAN) may not function under Red Hat\* Linux 6.2 64bit OS.

Implication You may not be able to wake system through onboard NIC port.

Status This issue may be fixed in a future LAN driver release.

Workaround None.

## Documentation Changes

---

None.