



Monthly Specification Update

***Intel® Server System P4000IP/R2000IP Family,
Intel® Workstation System P4000CR Family***



July, 2012

Enterprise Platforms and Services Marketing

Revision History

| Date | Modifications |
|-------------|---|
| April, 2012 | Initial release. |
| July, 2012 | Add errata 20,21,22,23,24 and update errata 6 and 8 |

Disclaimers

The Monthly Specification Update Server System may contain design defects or errors known as errata that may cause the product to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel®'s Terms and Conditions of Sale for such products, Intel® assumes no liability whatsoever, and Intel® disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel® sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Itanium, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2012.

Contents

Preface..... 1

 Nomenclature 1

 Product Scope 1

Summary Tables of Changes 2

Errata 4

 1. Linux Operating Systems are not supported using the RSTe mode..... 4

 2. UEFI Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode 4

 3. UEFI Operating System installation is not supported using the ESRT2 mode 4

 4. HDD status LEDs do not function under specific configuration 5

 5. RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports 5

 6. BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller 5

 7. System may halt under specific BIOS configurations..... 6

 8. Microsoft Windows 2003* x86 installation failure occurs using the “Pass-Through” mode of the SCU controller 6

 9. System may halt under unsupported configuration in ESRT2 mode 6

 10. Extra events may be seen in the System Event Log (SEL) during system global reset 7

 11. System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs 7

 12. Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero 8

 13. Integrated BMC Web Console – Power Control page – Perform Action button not functional 8

 14. IPMI Get Chassis Status command returns incorrect Chassis Identify State 8

 15. The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility(OFU) under SuSE Linux Enterprise Server 11* (64-bit) with SP2..... 9

 16. BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under the ESRT2 mode of the SCU controller 9

 17. High CPU utilization may occur when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC driver..... 9

 18. Bios/ME cannot update using OFU utility after S3 resume on P4000CR System .10

 19. System cannot go to S3 status in UEFI OS on P4000CR System 10

 20. Intel® RAID C600 Upgrade Key replacement Issue 10

 21. Intel® LAN driver installation failure on Windows* 7 11

 22. Hard drives connected through SAS expander can't be detected in legacy mode 11

 23. System will boot from on-board video although install add-in video card 11

Documentation Changes 13

<This page is intentionally left blank.>

Preface

This document is an update to the specifications contained in the *Intel® Server/Workstation Board S2600IP/W2600CR and Intel® Server/Workstation System P4000IP/CR, R2000IP Technical Product Specification*. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain specification changes, specification clarifications, errata, and document changes.

Nomenclature

1. **Specification Changes** are modifications to the current published specifications for Intel® server boards. These changes will be incorporated in the next release of the specifications.
2. **Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.
3. **Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.
4. **Errata** are design defects or errors. Errata may cause the server board behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that processor stepping are present on all devices.

Product Scope

The following specific boards, BIOS and components are covered by this update:

| Product Code | Baseboard PBA Revision | BIOS Revision | BMC Revision | FRU/SDR Revision | ME Revision |
|--------------|------------------------|---------------|--------------|------------------|--------------|
| P4000IPL | G59237-301 | 01.01.1002 | 1.00 | 1.03 | 02.01.05.069 |
| P4000CRL | G59236-301 | 01.01.1002 | 1.00 | 1.03 | 02.01.05.069 |
| P4000IP | G20993-303 | 01.02.0005 | 1.00 | 1.03 | 02.01.05.091 |
| P4000CR | G21602-302 | 01.02.0005 | 1.00 | 1.03 | 02.01.05.091 |
| R2000IP | G20993-303 | 01.02.0005 | 1.00 | 1.03 | 02.01.05.091 |

Summary Tables of Changes

The following tables provide an overview of known errata and known document changes that apply to the specified Intel Server Products. The tables use the following notations:

Doc: Intel intends to update the appropriate documentation in a future revision.

Fix: Intel intends to fix this erratum in the future.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

Shaded: This erratum is either new or has been modified from the previous specification update.

Table 1. Errata Summary

| No. | Plans | Description of Errata |
|-----|-------|---|
| 1. | Fix | Linux Operating Systems are not supported on RSTe mode |
| 2. | Fix | UEFI Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode |
| 3. | Fix | UEFI Operating System installation is not supported on ESRT2 mode |
| 4. | Fix | HDD status LEDs do not function under specific configuration |
| 5. | Fix | RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports |
| 6. | Fixed | BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller |
| 7. | Fix | System may halt under specific BIOS configurations |
| 8. | Fixed | Microsoft Windows 2003* x86 installation failure under Pass-through mode of SCU controller |
| 9. | Fix | System may halt under unsupported configuration in ESRT2 mode |
| 10. | Fixed | Extra events may be seen in the System Event Log (SEL) during system global reset |
| 11. | Fixed | System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs |
| 12. | Fix | Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero |
| 13. | Fix | Integrated BMC Web Console – Power Control page – Perform Action button not functional. |
| 14. | Fix | IPMI Get Chassis Status command returns incorrect Chassis Identify State |
| 15. | Fix | The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility(OFU) under SuSE Linux Enterprise Server 11* (64-bit) with SP2 |
| 16. | Fix | BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under ESRT2 mode of the SCU controller |
| 17. | Fix | High CPU utilization may occur when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC driver |
| 18. | Fixed | Bios/ME cannot update using OFU utility after S3 resume on P4000CR System |
| 19. | Fixed | System cannot go to S3 status in UEFI OS on P4000CR System |
| 20. | Fixed | Intel® RAID C600 Upgrade Key replacement Issue |
| 21 | Fix | Intel® LAN driver installation failure on Windows* 7 |
| 22 | Fix | Hard drives connected through SAS expander can't be detected in legacy mode |

| No. | Plans | Description of Errata |
|-----|-------|--|
| 23 | Fixed | System will boot from on-board video although install add-in video card |
| 24 | Fix | On-board VGA cannot be set to the highest resolution (1920x1080 and higher). |

Table 2. Documentation Changes

| No. | Plans | Document Name | Description of Documentation Change |
|-----|-------|---------------|-------------------------------------|
| 1. | | | |
| 2. | | | |
| 3. | | | |
| 4. | | | |

The following sections provide in-depth descriptions of each erratum/documentation change indicated in the tables above. The errata and documentation change numbers referenced in the following sections correspond to the numbers in the tables above.

Errata

1. Linux Operating Systems are not supported using the RSTe mode

| | |
|-------------|--|
| Problem | Intel® RSTe mode is not supported on Red Hat* Linux and SUSE* Linux. |
| Implication | User may not be able to install Red Hat* Linux and SUSE* Linux on Intel® C600 Series Chipset based Server Boards under Intel® RSTe mode. |
| Status | This issue may be fixed in a future driver or BIOS release. |
| Workaround | None. |

2. UEFI Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode

| | |
|-------------|--|
| Problem | System may encounter blue screen when installing Windows Sever 2008* R2 SP1 under UEFI with below configurations: <ul style="list-style-type: none">i. Intel® C600 RAID Upgrade Key is installed and SAS HDDs are used on SCU ports.ii. BIOS options “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are enabled.iii. RSTe RAID mode is used. |
| Implication | User may not be able to install UEFI Windows Server 2008* R2 SP1 on Intel® C600 Series Chipset based Server Boards with the above mentioned configuration. |
| Status | This issue may be fixed in a future BIOS release. |
| Workaround | None. |

3. UEFI Operating System installation is not supported using the ESRT2 mode

| | |
|---------|--|
| Problem | UEFI OS installation of Windows*, Red Hat* Linux or SUSE* Linux may fail on AHCI or SCU controller when “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are both enabled. |
|---------|--|

| | |
|-------------|--|
| Implication | User may not be able to install UEFI OS under the ESRT2 mode on Intel® C600 Series Chipset based Server Boards |
| Status | This issue may be fixed in a future BIOS revision. |
| Workaround | None. |

4. HDD status LEDs do not function under specific configuration

| | |
|-------------|--|
| Problem | If drives are connected through expander to SCU ports and configured under RSTe mode, the HDD status LEDs may not function properly. |
| Implication | HDD status LED may not show the HDD locate, HDD fault or RAID rebuild message. |
| Status | This issue may be fixed in a future RAID driver. |
| Workaround | None. |

5. RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports

| | |
|-------------|--|
| Problem | When Microsoft Windows 2008* R2 is installed on SCU ports, the installation of RSTe drivers and the Graphic User Interface (GUI) in Windows 2008* R2 will fail, if the AHCI controller is enabled, and no devices are attached to the AHCI SATA ports. |
| Implication | User may not be able to install RSTe GUI under mentioned configuration when the AHCI controller is enabled and no devices are attached to the AHCI SATA ports. |
| Status | This issue may be fixed in a future RAID driver. |
| Workaround | The workaround is to either plug a SATA device into one of the AHCI SATA ports or disable the onboard AHCI controller in BIOS |

6. BMC continuously sends RAID volume rebuild event in RSTe mode of the SCU controller

| | |
|---------|---|
| Problem | When RSTe RAID is in degraded mode and a drive is inserted to start the RAID rebuild, System Event Log (SEL) records drive plug and rebuild events and then continuously sends a rebuild event message. |
|---------|---|

| | |
|-------------|---|
| Implication | User may see the SEL flooded with RAID volume rebuild event entries. |
| Status | This issue was fixed in the latest RSTe driver ver 3.0.0.3020 upd 2012.02.03. |
| Workaround | None. |

7. System may halt under specific BIOS configurations

| | |
|-------------|---|
| Problem | Once BIOS options “EFI Optimized Boot” and “Memory Mapped I/O Above 4GB” are enabled, and RSTe mode is selected, system may halt during POST. |
| Implication | User may see system hang with the above mentioned configuration. |
| Status | This issue may be fixed in a future RSTe UEFI driver release. |
| Workaround | None. |

8. Microsoft Windows 2003* x86 installation failure occurs using the “Pass-Through” mode of the SCU controller

| | |
|-------------|--|
| Problem | Microsoft Windows Server 2003* x86 installations on SCU RSTe “pass-through” mode fail. |
| Implication | User may not able to install Microsoft Windows Server 2003* x86 on the above mentioned BIOS configuration. |
| Status | This issue was fixed in the latest RSTe driver ver 3.0.0.3020 upd 2012.02.03 |
| Workaround | None. |

9. System may halt under unsupported configuration in ESRT2 mode

| | |
|-------------|--|
| Problem | If no Intel® C600 RAID upgrade key (any of RKSAS4, RKSAS4R5, RKSAS8, RKSAS8R5) is installed to enable SAS support capability under the ESRT2 mode and SAS drivers are used, the system may halt at the boot stage. |
| Implication | User may see a system halt with no RAID keys installed with SAS drivers used and ESRT2 enabled. User should use SATA drives only if no RAID key installed. |
| Status | This issue may be fixed in a future BIOS release. |

Workaround None.

10. Extra events may be seen in the System Event Log (SEL) during system global reset

Problem The BMC may sporadically log extra reset event during a system DC reset (global reset). These events may appear as there is an extra reset during BIOS POST.

The following SEL entries indicate two resets in a POST process:

Informational event: Pwr Unit Status reports the power unit is powered off or being powered down.

Informational event: Pwr Unit Status reports the power unit is powered off or being powered down.

Implication The SEL log may indicate that system has an occasional reset in a normal POST during DC cycle test (global reset).

Status This issue was fixed in BMC 1.04.

Workaround None.

11. System may continuously report a faulty or assert/deassert log when having blank HDD carriers or un-configured HDDs

Problem With ESRT2 SATA RAID 5 config with 3 HDDs, put the 4th HDD in drive carrier and set it to either unconfigured or global hot spare. System event log may be flooded with HDD faulty entries.

With ESRT2 SAS RAID 1 with 2 HDDs, put 3rd HDD and set to unconfigured or global hot spare. System event log may be flooded flood with HDD faulty entries.

Implication User may see the SEL flooded with HDD faulty entries when either of the two scenarios above are used.

Status This issue was fixed in BMC 1.04.

Workaround None.

12. Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero

| | |
|-------------|--|
| Problem | On some systems the Integrated BMC Web Console Power Statistic page may display the Minimum wattage as zero (0W) after the system has been powered. This reading will stay at zero until the next power cycle of the system. |
| Implication | This is an incorrect reading only and does not affect operation. |
| Status | This issue may be fixed in a future BMC release. |
| Workaround | None. |

13. Integrated BMC Web Console – Power Control page – Perform Action button not functional

| | |
|-------------|--|
| Problem | After performing a Graceful shutdown from the Integrated BMC Web Console Power Control page the Perform Action button is greyed out and cannot be pressed to request another action. |
| Implication | You cannot perform a power on of the system. |
| Status | This issue may be fixed in a future BMC release. |
| Workaround | Select another page in the Integrated BMC Web Console and then return to the Power Control Page. The Perform Action button will then be available. |

14. IPMI Get Chassis Status command returns incorrect Chassis Identify State

| | |
|-------------|---|
| Problem | When a Get Chassis Status command is issued, after the Chassis Identify LED has been forced on, the status of off (00b) is returned for Chassis Identify State (response data byte 4 – bits [5:4]). |
| Implication | Unable to correctly read when the Chassis Identify LED is on. |
| Status | This issue may be fixed in a future BMC release. |
| Workaround | None. |

15. The BIOS and ME Firmware can't be updated successfully via Intel® One Boot Flash Update Utility(OFU) under SuSE Linux Enterprise Server 11* (64-bit) with SP2

| | |
|-------------|---|
| Problem | OFU will fail to update BIOS & ME under SuSE Linux Enterprise Server 11* (64-bit) with SP2 Operating System. |
| Implication | If the system is running SuSE Linux Enterprise Server 11* (64-bit) with SP2 Operating System, using OFU to update System Firmware Update Package(SFUP) will fail. |
| Status | This issue may be fixed in a future OFU version. |
| Workaround | Update System Firmware Update Package(SFUP) from EFI environment using iFlash32, FWPIAUpdate and FRUSDR Utility. |

16. BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under the ESRT2 mode of the SCU controller

| | |
|-------------|--|
| Problem | HDD fault will keep asserting and de-asserting frequent during RAID rebuild under ESRT2. |
| Implication | During HDD ESRT2 RAID rebuild, there's flood HDD fault assert/deassert(SAS RAID) or Rebuild/remap (SATA RAID) logs into SEL. |
| Status | This issue may be fixed in a future BIOS release. |
| Workaround | None. |

17. High CPU utilization may occur when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC driver

| | |
|-------------|--|
| Problem | There has been high CPU load observed when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC (Network Interface Card) driver. |
| Implication | When the ports are not electrically "linked" and the embedded driver is loaded the DPC rate steadily increases until the system slows to the point where it is essentially unusable. |
| Status | This issue may be fixed in a future driver release. |
| Workaround | None. |

18. Bios/ME cannot update using OFU utility after S3 resume on P4000CR System

| | |
|-------------|--|
| Problem | BIOS/ME update under OS will fail after S3 resume. |
| Implication | Can not update Bios and ME with OFU utility. |
| Status | This issue was fixed in Bios 01020004. . |
| Workaround | None. |

19. System cannot go to S3 status in UEFI OS on P4000CR System

| | |
|-------------|---|
| Problem | System Cannot goto S3 status in UEFI native OS. |
| Implication | System will lose S3 function if use UEFI native OS. |
| Status | This issue was fixed in Bios 01020004. |
| Workaround | None. |

20. Intel® RAID C600 Upgrade Key replacement Issue

| | |
|-------------|---|
| Problem | With Manageability Engine (ME) Firmware 02.01.05.069, the server may detect the incorrect Storage Control Unit (SCU) Redundant Array of Inexpensive/Independent Disks (RAID) information after installing or replacing the RAID upgrade key. The board or system may still show the previous RAID information even if you replace the key with a new one. |
| Implication | With the ME firmware 02.01.05.069, the system may not detect the new RAID activation key during the first time AC power on. |
| Status | The issue is fixed with ME firmware 02.01.05.091. |
| Workaround | Do a second AC power cycle to the system after the RAID upgrade key has been installed or replaced to ensure the correct type of key is identified. |

21. Intel® LAN driver installation failure on Windows* 7

| | |
|-------------|--|
| Problem | The Intel® LAN driver version 16.8 and below may not be installed successfully on Windows* 7 with the .bat installation scripts in the driver package. |
| Implication | The LAN driver can not be installed by the .bat installation scripts in the driver package. |
| Status | The issue may be fixed in a future Intel® LAN driver |
| Workaround | Two workarounds are available: <ol style="list-style-type: none">1. The LAN driver can be manually installed.2. User can lower the “User Account Control” to “Never Notify”, then the driver can be installed with the .bat installation scripts. |

22. Hard drives connected through SAS expander can't be detected in legacy mode

| | |
|-------------|--|
| Problem | If hard drives are connected through expander to SCU ports and configured under RSTe mode, the hard drives can't be detected by system in legacy mode (default BIOS setting). |
| Implication | Users can't use the hard drives connected through expander as boot device to install OS. But users can install OS to other hard drives which are not connected through expander and load RSTe driver to make the hard drives connected through expander visible to OS. Or users can change Boot Options -> EFI Optimized Boot to “Enabled” in BIOS Setup so that hard drives connected through expander can be detected by the system. |
| Status | This issue may be fixed in a future BIOS release. |
| Workaround | None. |

23. System will boot from on-board video although install add-in video card

| | |
|-------------|---|
| Problem | When try to boot from add-in video card, system can not boot up. |
| Implication | Bios video output policy by default was booting from onboard video although install the add-in video card. |
| Status | This issue was fixed in Bios 01.02.0009 and changed video output to installed add-in video card by default. |

Workaround Need to install internal video cable to boot up system first then disable on-board video option in Bios.

24. On-board VGA cannot be set to the highest resolution (1920x1080 and higher).

Problem The Graphics ID register in the on-board video controller is getting set incorrectly.

Implication The video cannot be set to the highest resolutions listed here:

[1920x1080,High 256 Color, 60 Hertz]
[1920x1200,High 256 Color, 60 Hertz]
[1920x1080,High Color(16bit), 60 Hertz]
[1920x1200,High Color(16bit), 60 Hertz]

Status This issue may be fixed in a future BMC release.

Workaround None.

Documentation Changes

None.