

This Technical Advisory describes an issue which affects product functionality, reliability or safety

Intel Technical Advisory

TA-915-7

5200 NE Elam Young Parkway Hillsboro, OR 97124

November 11, 2008

BIOS may cause Non-Maskable Interrupts (NMI) during boot

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The products listed in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

- MFSYS25
- MFS5000SI
- MFS5000SIB
- S5000PSLR
- S5000XVNR
- S5000XVIAR
 S5000PALR
- SR2500ALLXR
- SR2500ALBRPR
- SR1550ALR
- SR1550ALSR
- SR1550ALSASR
- S5000VSAR
- SR2520SAXSR
- SR2520SAXR
- SR2520SAFR

- S5000VCLR
- SR1530HCLR
- SR1530HCLSR
- SR1530CLR
- T5000PAL
- NSC2U
- TIGH2U
- S5000PHB
- TIGW1U
- NSW1U
- SSR212MC2

Description

An issue has been discovered by an Intel customer implementing Intel[®] Xeon[®] Processors 5400 Series E-0 stepping and BIOS R0091 or Intel[®] Modular Server BIOS R0047. Approximately one out of three boots will exhibit an NMI with one or more of the following characteristics:

- Immediately following POST, the following error may be seen: "NMI detected. System Halted", followed by a system hang.
- No POST, no video (system hang).
- System hang with the following POST Code LED indicators: MSB off | off | green | amber LSB
- In some instances uncorrectable memory errors may be falsely reported in the System Event Log (SEL) and DIMM's C1 and D1 may be taken offline.

Root Cause

Some combinations of processor and memory speeds created a timing issue that resulted in application processors (APs) being out of synchronization. When BIOS code is executed on APs that are out of synchronization an NMI is generated.

Corrective Action / Resolution

During Power-on self-test (POST) several milliseconds of delay were added after commands that request all APs to run the same code. This ensures all APs are synchronized before continuing BIOS execution.

Intel[®] Modular Server UFU 2.6 (which includes BIOS R0048.1) will be available in late November 2008 and includes fixes for all known issues. Intel[®] Modular Server BIOS R0050 is planned for release in Q1'09 and will be communicated via the normal release process.

Production BIOS 94 planned for release on November 11th, 2008 is now expected no later than November 13th, 2008 for the products listed below. BIOS 94 will include the following changes:

- Fixed Midplane2 beep sound during POST for S5000PAL/S5000XAL.
- Recent Intel[®] RAID cards ctrl+G fails in S5000PSL/S5000XVN PCI slot 4.
- System won't POST with some Gigabit LAN adapters installed in x8 slots.
- Fixed BIOS89 failure on Platform Compatibility Test (PCT) for S5000PSL and S5000PAL.
- Fixed certain video cards stop Windows* XP Professional 32bit Service Pack 2 (SP2) from shutting down in S5000XVN.
- Fixed Issue with BIOS91 and the Intel® Xeon® Processors 5400 Series E-0.
- Fixed Intel® Xeon® Processor E5405 processor power down issue.
- Fix NMI and SEL log policy for Fatal and Non Fatal Memory Errors.

OTHER:

- Added workaround for the board signal integrity issue requiring a manufacturing change for some products. Note this workaround may be used on both older and newer motherboards.
- Add Qimonda* AMB patch to MRC 1.32 in efforts to reduce M1Err(s).
- Improve remote console performance at 9600 baud rate.
- Update to LSI* SATA SW RAID OpRom v A.07.05151334I.

The table below recommends specific BIOS releases to be used with different platform/processor configurations:

Platform	Intel [®] Xeon [®] processors	Intel [®] Xeon [®] processor	Intel [®] Xeon [®] processor
	5100, 5200, 5300 series	5400 series, C-0 stepping	5400 series, E-0 stepping
S5000PSLR	BIOS R91, R91.6 or R94	BIOS R91, R91.6 or R94	BIOS R91.6 or R94
S5000PALR			
SR2500ALLXR			
SR2500ALBRPR			
SR1550ALR			
SR1550ALSR			
SR1550ALSASR			
S5000VSAR			
SR2520SAXSR			
SR2520SAXR			
SR2520SAFR			
S5000VCLR			
SR1530HCLR			
SR1530HCLSR			
SR1530CLR			
T5000PAL			
NSC2U			
TIGH2U			
S5000PHB			
TIGW1U			

NSW1U SSR212MC2			
S5000XVNR	BIOS R91 or R91.6	BIOS R91 or R91.6	BIOS R91.6
MFSYS25	UFU P2.3.1 or P2.3.5	UFU P2.3.1 or P2.3.5	UFU P2.3.5
MFS5000SI MFS5000SIB	BIOS R43 or R48.1	BIOS R43 or R48.1	BIOS R48.1

ATTENTION: Customers using Intel[®] Workstation S5000XVN Should **not** use BIOS 94 but should remain on BIOS 91.6 until a replacement BIOS is available in December 2008.

Intel will also review the BIOS evaluation process to determine how this type of issue can be found during validation.

Recommended Customer Action

Customers using the following processors can continue using BIOS R0091/Intel® Modular Server BIOS R0047:

- Intel[®] Xeon[®] processors 5100, 5200, 5300 series, any stepping, with the products listed above or
- Intel[®] Xeon[®] processor 5400 series, C-0 stepping, with the products listed above.

Customers using Intel[®] Xeon[®] processor 5400 series, E-0 stepping, must upgrade to BIOS R0091.6/Intel[®] Modular Server BIOS R0048.1 or later.

Versions of BIOS before R0091/Intel[®] Modular Server R0047 can be upgraded to BIOS R0091.6/Intel[®] Modular Server R0048.1 using any supported Intel[®] Xeon[®] processor 5000 sequence.

Intel recommends customers perform a shortened validation run with BIOS R0091.6 for the Intel Workstation S5000XVN/Intel® Modular Server BIOS R0048.1 and perform a normal validation run with BIOS R0094/Intel® Modular Server BIOS R50 when available.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division Intel Corporation