



*This Technical Advisory describes an issue which may or may not affect the customer's product*

# Intel Technical Advisory

TA-923-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

December 26, 2008

## Intel® Deployment Assistant v2.5 May Fail to Upgrade Server System Firmware

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Deployment Assistant v2.5 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

### Products Affected

Product Code	MM#
Intel® Server Board S5000VCL	896204, 896205
Intel® Server System SR1530CL, SR1530HCL, SR1530HCLS	892052, 892053, 892054, 892060, 892047
Intel® Server Board S5000VSA	901741, 901744, 901745, 901746
Intel® Server System SR2520SAF, SR2520SAX, SR2520SAXS	900456, 900457, 900459, 900476, 900478, 900487

### Description

Intel® Deployment Assistant v2.5 CD P.N. D36614-008 for Intel® Server Board S5000VSA, Intel® Server System SR2520SAF / SR2520SAX / SR2520SAXS and CD P.N. D48899-008 for Intel Server Board S5000VCL, Intel® Server System SR1530CL / SR1530HCL / SR1530HCLS may fail to update server system firmware including BIOS, BMC firmware and SDR. IDA may report that the server system firmware upgrade process completed successfully even though it has actually failed.

### Root Cause

Intel found the server system firmware upgrade in Intel® Deployment Assistant v2.5 has a defect on Intel® Server Board S5000VSA, Intel® Server Board S5000VCL, Intel® Server System SR2520SAF / SR2520SAX / SR2520SAXS and Intel® Server System SR1530CL / SR1530HCL / SR1530HCLS . This defect causes server system firmware upgrades to randomly fail.

### Corrective Action / Resolution

A new build of the Intel Deployment Assistant is being created to fix this bug and will be posted to <http://support.intel.com> in the near future.

In the interim, customers can download the DOS version Firmware Update Package from <http://downloadcenter.intel.com/default.aspx> to upgrade server system firmware in DOS environment.

Enterprise Platforms & Services Division  
Intel Corporation