

intel® Technical Advisory

TA-703-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

July 28, 2004

Intel® E7525 MCH Interrupt Message Re-Ordering across Hub Interface Erratum: Impact to Intel® Server Board SE7525GP2

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel Server Board SE7525GP2** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product Code	MM #
BGPE7525	856625
SE7525GP2	856659

Description

An erratum affecting PCI Express* slot capabilities has been found in the Intel® E7525 server chipset during testing and is root caused. Please reference *Intel® E7525 MCH Specification Update Erratum #24: "Interrupt Message Re-Ordering across Hub Interface Erratum"* for a complete description of the MCH errata. The Intel® Server Board SE7525GP2 is affected by this erratum.

Intel Server Board SE7525GP2 based systems running with a single processor thread and operating in legacy PIC mode or virtual wire Mode A may hang under high I/O-driver interrupt stress. For systems operating in full APIC mode where the number of virtual interrupt line (intA, intB, etc.) used by all PCI-Express adapters in a system exceeds the number of logical processors (threads), the system may hang.

Root Cause

Please reference *Intel® E7525 MCH Specification Update Erratum #24: "Interrupt Message Re-Ordering across Hub Interface Erratum"* for a complete description of the MCH errata.

Corrective Action / Resolution

Intel Server Board SE7525GP2 PCI Express add-in adapter card support is limited to single function devices. PCI Express add-in adapter cards tested and supported with the Intel Server Board SE7525GP2 will be listed in the *Intel Server Board SE7525GP2 Tested Hardware and Operating System List* (THOL) document.

A BIOS workaround is required for PIC mode operation. The BIOS workaround will be incorporated into Intel Server Board SE7525GP2 BIOS Production Release Version P04. Intel recommends that customers update all Intel® Server Board SE7525GP2 to this BIOS version. BIOS Version P04 will be available from iBL and <http://support.intel.com> on or before August 27, 2004.

Customers may choose to ship Intel Server Board SE7525GP2 product with BIOS Production Release Version P03, which does not include the PIC mode BIOS workaround, if the system configuration adheres to the following limitations: 1) Uni-processor systems must have processor hyperthreading Enabled in BIOS Setup, 2) The operating system must be configured to operate in symmetric mode rather than PIC mode, and 3) Only PCI Express single function add-in adapters are installed. This restricted configuration will limit any possible exposure to this issue to pre operating system boot.

intel[®] Technical Advisory

TA-703-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

July 28, 2004

An MCH component stepping change will be implemented on the Intel Server Board SE7525GP2 in early Q4 2004 to add support for broad PCI Express* adapter add-in cards.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation