

## **Driver and WHQL Engineering Services**

**Motherboard Logo Program (MLP)** 

# Intel<sup>®</sup> Desktop Board D975XBX

# **MLP** Report

2/7/2006

#### **Purpose:**

This report describes the D975XBX Motherboard Logo Program testing run conducted by Intel<sup>®</sup> Driver and WHQL Engineering Services (DWES).

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

\* Other names and brands may be claimed as the property of others.

Copyright  $\ensuremath{@}$  2003, Intel Corporation. All rights reserved.

## **Contents**

Introduction	5
Overview of Contents Error! Bookn	nark not defined.
Terms and Definitions	
Desktop Board Configuration	6
Desktop Board D975XBX Final Configuration Report: Completion of MLP	6
Board Information	
Product	
Processor	
System Memory	6
BIOS Error! Bookn	mark not defined.
Power Management	6
Operating System Tested	6
Onboard Integrated Devices and Driver	
Hardware Compatibility Tests Used (HCT)	7
Errata and Contingencies	8
Test Notes	8

## Introduction

#### **Terms and Definitions**

Term	Definitions	
WHQL	Windows* Hardware Qualification Lab	
HCT	Hardware Compatibility Tests	
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx	
HCL	Windows Hardware Compatibility List. You can view the HCL at: http://www.microsoft.com/hwdq/hcl/	

## **Desktop Board Configuration**

#### Desktop Board D975XBX Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

#### **Board Information**

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)	
D975XBX	BX97510J.86A.0212.1017.2005.1350	N/A - all technologies logo'd	
Processor			
Speed	3.8 GHz		
Family	Pentium <sup>®</sup> 4		
Bus Speed	800 MHz		
Form Factor	LGA775		
Connector Type	LGA775 Socket		
System Memory			
Amount Installed	1024 MB		
Speed	Dual Channel, DDR2, 533		
Memory Type	DIMM		
Connector Type	DDR, 240 Pin		
Power Management			
BIOS Setting	S3		
Operating System Tested			
	Check Tested	Comments	
Windows XP Pro	☑	Service Pack 2	
Windows XP Pro 64-bit	Service Pack 1		

<sup>&</sup>lt;sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

#### **Onboard Integrated Devices and Driver**

Technology	os	Version
Chipset Update Utility	Windows XP Pro	7.0.0.19
Intel <sup>®</sup>	Windows XP Pro 64-bit	7.0.0.19
Graphics	Windows XP Pro	6.14.10.4299
NVidia 5300	Windows XP Pro 64-bit	6.14.10.4299
Audio	Windows XP Pro	5.10.4647.4
Sigmatel	Windows XP Pro 64-bit	5.10.4647.4
LAN	Windows XP Pro	9.2.24.0
Intel® PRO Network Connections	Windows XP Pro 64-bit	9.2.24.0
SATA/RAID	Windows XP Pro	1.2.3.1
Silicon Image	Windows XP Pro 64-bit	1.2.3.1
SATA/RAID	Windows XP Pro	5.1.0.1022
Intel <sup>®</sup>	Windows XP Pro 64-bit	5.1.0.10.22
USB 2.0	Windows XP Pro	7.0.0.19
Intel <sup>®</sup>	Windows XP Pro 64-bit	7.0.0.19
IEEE1394b	Windows XP Pro	N/A
Texas Instruments	Windows XP Pro 64-bit	N/A
TPM ST Microelectronics	Windows XP Pro	1.0.0.9
	Windows XP Pro 64-bit	1.1.0.5

#### **Hardware Compatibility Tests Used (HCT)**

Microsoft website: <a href="http://www.microsoft.com/whdc/hwtest/system/default.mspx?area=SysSrv-dsktp">http://www.microsoft.com/whdc/hwtest/system/default.mspx?area=SysSrv-dsktp</a>. Please check regularly for test kit updates. Not responsible for broken links caused by changes to Microsoft's Web Site.

Operating Systems	Notes	нст
Windows XP Pro Windows XP Pro 64-bit	HCT 12.1.01 for Windows XP SP2	HCT 12.1.01 Test Procedure and Readme Downloads

### **Errata and Contingencies**

		ID		
Operating System	Failing Test	Number	Туре	Error Description
Windows XP Pro Windows XP Pro 64-bit	System Stress	1390	Errata	A5C.2C0: pokefocs.exe died. A5C.2C0: ExitCode: 0. And A5C.2C0: pokefocs.exe: A5C.2C0: DIED
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1399	Errata	GetConfigDefault: Response == 0x80000000B7031110 GetConfigDefault(F1F): Response == 0x0006F6E4B7031110 Error: Codec must either respond to F1F control identically to F1C or respond with 0
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1457	Errata	Error: Location field can not be 0. Error: ConnectionType field can not be 0. Error: Color field can not be 0. Error: DefaultAssociation field can not be 0.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1388	Errata	Error: If the DefaultAssociation is set to 0x0F, then the Sequence number must be 1. Error: Sequence field can not be 0.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1398	Errata	Global Control = 0x00000001 Accept Unsolicited Response Enable -UNSOL = 0x00 FAIL : Accept Unsolicited Response Enable -UNSOL is not RW FAIL: Accept Unsolicited Response Enable -UNSOL is not RW
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	2965	Incident	SDx Input Stream Descriptor Control_3 = 0x04 Assertion Testing for Read Write: Testing Assertion Testing for Read Write: FAILED.
Windows XP Pro Windows XP Pro 64-bit	UAA Test Application	1463	Errata	Start Case: ID 37:2 : Codec Tests\RequiredVerbSupport:[date of test] (several lines of function calls and returns) End Case: ID 37:2 : FAIL : Codec Tests\RequiredVerbSupport : [date of test]
Windows XP Pro Windows XP Pro 64-bit	LAN Device Wake-up	772	Errata	This test is not required for Gigabit and higher Ethernet devices.

#### **Test Notes**

Operating System	Test	Description