



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0952-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

May 19, 2010

Intel® Server Board S5520HCT with PBA number E80888-552 does not support Intel® Trusted Execution Technology (Intel® TXT)

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel products described herein may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product Name	MM#	TA#	PBA#
S5520HCT	904912	E84149-551	E80888-552

Description

A PCN109903 has been recently published to indicate that Intel® TXT feature support requires latest PVMT version onboard TPM chip. Intel® server board S5520HCT (PBA# E80888-552) does not support the Intel® TXT feature due to the old PVLV version TPM chip.

The Minimum hardware requirements for Intel® TXT are:

Processor: B1 or later stepping Intel® Xeon Processor 5600 Series
Server Board: Intel® Server Board S5520HCT; **PBA version E80888-553 or later**
Memory: At least 1 GB memory installed

Detail steps to enable Intel® TXT can be found in the Intel® Server Board S5520HCT Technical Product Specification from the Intel website at:

<http://www.intel.com/support/motherboards/server/s5520hc/sb/CS-030223.htm>

Corrective Action / Resolution

Intel will provide warranty replacement for Intel® server board S5520HCT (PBA# E80888-552) customers who require Intel® TXT feature support.

Please contact Intel using your normal warranty process, indicating that you are calling regarding TA-952-1. Have the following information when you call: the TA/PBA number(s) of the affected board(s), system(s) or chassis(s); and the MM#, Product Code and/or part number of the affected item needed.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation