FIC Products with CPU& BIOS Status

AMDK75 based board :

Model Name		**AT31**				
PCB Version		**1.3**	**1.3**	**1.4**		
BIOS Version		**TBA41**	**TBA42**	**TBA42**		
Flash Utility		**Flash818**	**Flash818**	**Flash818**		
AMD						
AMD Athlon-900	100x9	V	V	V		
AMD Athlon-950	100x9.5	V	V	V		
AMD Athlon-1G	100x10					
AMD Athlon-1.1G	100x11	V	V	V		
AMD Athlon-1.2G	100x12					
AMD Athlon-1.3G	100x13	V	V	V		
AMD Athlon-1.4G	100x14	V	V	V		
AMD Athlon-1G	133x7.5					
AMD Athlon-1.133G	133x8.5	V	V	V		
AMD Athlon-1.2G	133x9					
AMD Athlon-1.333G	133x10	V	V	V		
AMD Athlon-1.4G	133x10.5	V	V	V		
Athlon XP 1500+ (Palomino/1333)	133	V	V	V		
Athlon XP 1600+ (Palomino/1400)	133	V	V	V		
Athlon XP 1700+ (Palomino/1467)	133	V	V	V		
Athlon XP 1700+ (Thoroughbred/1467)	133	V	V	V		
Athlon XP 1800+ (Palomino/1533)	133	V	V	V		
Athlon XP 1800+ (Thoroughbred/1533)	133	V	V	V		
Athlon XP 1900+ (Palomino/1600)	133	V	V	V		
Athlon XP 1900+ (Thoroughbred/1600)	133	V	V	V		
Athlon XP 2000+ (Palomino/1667)	133	V	V	V		
Athlon XP 2100+ (Palomino/1733)	133	V	V	V		
AMD Duron-900	100x9	V	V	V		
AMD Duron-950	100x9.5	V	V	V		
Duron 1.0GHz (Morgan)	100x10					
Duron 1.1GHz (Morgan)	100x11	V	V	V		
Duron 1.2GHz (Morgan)	100x12					
Duron 1.3GHz (Morgan)	100x13	V	V	V		

Socket A Fan-Sink: Please refer to AMD's Web side recommendation. Especially, over 850 Mhz CPUs.

Remark: V…Support