



Windows Vista Premium Certification

Intel® Desktop Board

DQ963FX

MLP Report

2/26/2007

Purpose:

This report describes the DQ963FX Motherboard Logo Program testing run conducted by Intel® Driver and WHQL Engineering Services (DWES).

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2007, Intel Corporation. All rights reserved.

Contents

- Introduction 4**
 - Terms and Definitions 4
- Desktop Board Configuration 5**
 - Desktop Board DQ963FX Final Configuration Report: Completion of MLP 5
 - Board Information 5
 - Product Code 5
 - Processor 5
 - System Memory 5
 - Power Management 5
 - Operating System Tested 5
 - Onboard Integrated Devices and Drivers 6
 - Driver Test Manager Used (DTM) 6
 - Errata and Contingencies 7
 - Test Notes 7

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
DTM	Driver Test Manager
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
TPL	Tested Products List. You can view the Windows Marketplace for tested products list at: http://testedproducts.windowsmarketplace.com/content.aspx?ctf=about.htm

Desktop Board Configuration

Desktop Board DQ963FX Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

Board Information

Product Code ¹	BIOS String/Model	Technologies NOT Logo'd (yet)
DQ963FX	MQ96510J.86A.1618.2007.0117.1535	N/A - all technologies logo'd
Processor		
Speed	3.8 GHz	
Family	Pentium® 4 Hyper Threading	
Bus Speed	800 MHz	
Form Factor	LGA775	
Connector Type	LGA775 Socket	
System Memory		
Amount Installed	4096 MB	
Speed	Dual Channel, DDR2, 667	
Memory Type	DIMM	
Connector Type	DDR2, 240 Pin	
Power Management		
BIOS Setting	S3	
Operating System Tested		
	Check Tested	Comments
Windows Vista Client	<input checked="" type="checkbox"/>	RTM Build 6000
Windows Vista Client 64-bit	<input checked="" type="checkbox"/>	RTM Build 6000

Onboard Integrated Devices and Drivers

Technology	OS	Version
Chipset Update Utility Intel® Chipset Software Utility	Windows Vista	8.1.1.1010
	Windows Vista 64-bit	8.1.1.1010
LAN Intel® PRO Network Connections	Windows Vista	11.2
	Windows Vista 64-bit	11.2
Audio Sigmatel	Windows Vista	6.10.0.5274
	Windows Vista 64-bit	6.10.0.5274
Graphics Intel® Graphics Media Accelerator	Windows Vista	7.14.10.1132
	Windows Vista 64-bit	7.14.10.1132
HECI Intel® Management Engine Interface	Windows Vista	2.1.22.1026
	Windows Vista 64-bit	2.1.22.1026

Driver Test Manager Used (DTM)

Microsoft website: <http://www.microsoft.com/whdc/DevTools/WDK/DTM.msp>

Please check regularly for test kit updates. Intel does not responsible for broken links caused by changes to Microsoft's Web Site.

Operating Systems	Notes	Testkit
Windows Vista Client Windows Vista Client 64-bit	DTM for Windows Vista	DTM for Windows Vista

Errata and Contingencies

Operating System	Failing Test	DTM Filter ID	Type	Error Description
Windows Vista Client Windows Vista Client 64-bit	PCI Compliance test	208	Errata	The PCI Compliance test is not required to pass until December 31st 2006.

Test Notes

Operating System	Test	Description
Windows Vista Client Windows Vista Client 64-bit	Audio Fidelity	Audio Fidelity test not required to pass by 1 st June 2007. Audio Fidelity tested on Audio Precision machine and are run separately from DTM tests. Note: This board is Vista Premium logo certified