

Attention!

The Intel® Pentium® III processor **550 MHz** requires a motherboard BIOS that is specifically designed to support it. Systems without the correct BIOS will not operate properly. Contact your motherboard supplier to ensure your motherboard BIOS supports the processor.

Copyright © Intel Corporation 1999.
Third-party brands and names are the property of their respective owners.

Part Number 745126-001
First Edition April 1999