

Date:4/1/03

Socket A Fan-Sink: Please refer to AMD's Web side recommendation. Especially, over 850 Mhz CPUs.

Remark: V...Support

By Louise