


VI11 with ALC650 Not Support SPDIF_IN

If your VI11 board has a label **ALC650** on the game port, the mainboard will not have SPDIF_IN features. The SPDIF_IN ports on the A73 card that mentioned in Page 2-17 Chapter 2 of this manual have no SPDIF_IN functions.



Also, in Page 2-6, VI11 Manual A0 version, add a note-



NOTE: The FSB frequency is set at 100 MHz, its default value. If users want to set at 133 MHz, please adjust the BIOS feature that mentioned in Page 3-17, **CPU Host/SDRAM/PCI Clock**.