

## Jumper Setting for CPU Clock

CPU Speed	External Clock	JK1	JK2	JK3	CPU Clock Rate	
					Int. Multiple	JC2
133 MHz	66 MHz				2 x Ext.	
120 MHz	60 MHz				2 x Ext.	
100 MHz	66 MHz				1.5 x Ext.	
90 MHz	60 MHz				1.5 x Ext.	
75 MHz	50 MHz				1.5 x Ext.	

## Jumper Setting for I/O

J1	<b>Display Type</b>
	Mono/EGA/VGA CGA
JCP	<b>Password Clear</b>
	Enabled Disabled (Default)
JI	<b>NS87332/87334</b>
	IR serial port (for NS334) COM Port (for NS332) (Default)